

SECRET

(When Filled In)

FILE INFO

CIA-2820

REPRODUCTION PROHIBITED

ACTION	1	6	11	16	
	2	7	12	17	
	3	8	13	18	
	4	9	14	19	
	5	10	15	20	

S E C R E T 081751Z NOV 71 CITE [redacted]

25X1A

IDEALIST [redacted]

25X1A

A. 0131A

B. 655

C. 5 NOV 1971-6.1

25X1A

D. [redacted]

E. (1) FLAPS WOULD NOT RETURN FROM GUST UP, AILERONS OK. FLAP CONTROL C/S POPPED; TRIED TO RESET TWICE, WOULD NOT RESET. C/A - SPLICED 3 BURNED WIRES NO. C48, C47, AND C45, LEFT WING STATION 265 REF BLUE PRINT RR47 REV 1 WING FLAP AND AILERON SHIFT.

(2) TRACKER HEATER OVERHEAT LIGHT CAME ON 1 HR AFTER T.O., BLOWER POSITION OK. TRIED HEATER BLOWER TWICE, BUT LIGHT CAME ON BOTH TIMES. C/A - REPLACED TRACKER HEATER BLOWER, S/N OUT 13R, S/N IN 34.

F THRU G. NONE.

S E C R E T

BT